

EXHAUST MANIFOLD REPAIR ROSINA™ - PROKIT™ REPAIR IT VS. REPLACE IT - FAST

ProMAXX® engineered a complete solution to repair the turbo charger "Y" pipe mounting on the 6.4L Ford/ INT'L Diesel Engine.

Key drivers:

- Save over 3 hours of repair time
- Increase service ledger profitability
- Repairs the Turbo Charger to better-than-new condition
- Does not require a Helicoil® insert
- Limited Lifetime Warranty
- Made in the USA.

Introducing the Rosina™ ProKit™ that continues the trend by delivering increased productivity in the repair. The device is proven to reduce repair times from about 3-4 hours to under 40 minutes. This newest device is engineered for the 6.4L Ford Engine manufactured by International, commonly found in 2008-2010 Ford trucks, school buses, motorhomes, and cab & chassis configuration. The design allows for on-the-truck repairs of the "Y" pipe mounting bolts to the turbo without a costly removal. This device is crazy good at making these repairs fast and hassle-free. We set out to design solutions to make these types of repairs easier, and over 8,000 technicians agree we achieved it.

**GET IT IN. GET IT DONE. GET IT OUT.
TAKE IT TO THE MAXX WITH PROMAXX®**

PROUDLY MADE
IN THE USA 



ABOUT PROMAXX® TOOL:

ProMAXX® Tool is a premium manufacturer of high-quality precision-engineered specialty tools for problematic repairs in Chrysler, Dodge, Ford, General Motors, Isuzu, International, Jeep, Lincoln and Mercedes Benz engines. Our products are designed, engineered, and manufactured right here in the United States.



Rosina™
ProKit™
S100APRO

Our mission at ProMAXX® is simple. Maximize the performance of the automotive technician by solving problematic repairs with unique, worry-free solutions that reduce costs, risks, and boost repair speeds—delivering more profitability to you and your operation.

PLATINUM TOOLING:

Precision tooling for more challenging repairs.



ProDrill™
(PLT125/PMXPLT125)

ProDrill™
(PLT188/PMXPLT188)

REPLACEMENT TOOLING:



ProDrill™
(SSSC188D/PMXSSSC188)

ProDrill™
(SSSC266/PMXSSSC266)

PHONE
412-347-4041

EMAIL
info@promaxxtool.com

WEBSITE
www.promaxxtool.com